




SURVEYOR'S CERTIFICATE

TO WHOM IT MAY CONCERN, I FRED W. MALAN do hereby certify that I am a Registered Land Surveyor, and that I hold Certificate No. 1441, as prescribed by the Laws of the State of Utah, and I have made a survey of the following described property:

A part of lots 14, 15, and 16, Block 2, Country Club Heights Subdivision, Beginning at a point on the North line of Gibbs Circle 9.4 feet Westerly from the SE Corner of said lot 14 and running thence N. 10°42' W. 45 feet; thence N. 40°42' W. to a point 20 feet South of the North line of said lot 14; thence N. 89°53' W. 163.8 feet to the East line of said lot 15; thence S. 0°05' W. 95 feet to a point 45 feet South of the NE corner of said lot 16; thence N. 86°25' W. 110.09 feet to a point on the Easterly line of Gibbs Circle 8.14 feet Northerly from the SW corner of said lot 15; thence to the left along the arc of a 50 foot radius curve 42.66 feet, the long chord bearing N. 56°46' W. a distance of 42.61 feet to the point of beginning.

July 15, 1958

Date

Job No. M36-24

Requested for;

Ernest Schneider
820 Ben Lomond Drive
Ogden, Utah

Fred W. Malan

Registered Land Surveyor Certificate No. 1441
Fred W Malan, 2960 Van Buren, Ogden, Utah

House No. 4141 Country Club Drive
Ernest Schneider Jr.