




WEST

EAST

NORTH

STREET



CONCRETE SIDEWALK


CONCRETE GUTTER

2375 WEST

ROLL GUTTER

ROLL MULCH PAVEMENT

CONCRETE SIDEWALK



LOCATION OF ACCIDENT
5445 SO. - 2375 W.
RD., UTAH

PLAT PREPARED BY
FRED W. MALAN LAND SURVEYOR
2960 VAN BUREN AVE #1441
OGDEN, UTAH 9-27-54
JOB #22-241

PLAT REQUESTED BY
MORTON C. ROUNDY CLAIM REPRESENTATIVE
N.M. FIRE ASSOCIATION, NORTHWEST CASUALTY CO.
515 JUDGE BLD. SALT LAKE CITY, UTAH

DRAWER A-18-85

SOUTH